

From: [Rodriguez, Jose](#)
To: [Kenny Blake](#)
Cc: [Ngo, Kim](#); [Baker, JohnE](#); [Bresnahan, Meaghan](#); [Mistry, Jatin](#)
Subject: RE: Well 1 Vent - Installed 09062017
Date: Thursday, September 21, 2017 4:12:00 PM
Attachments: [image002.gif](#)
[#13 - Seal the Gap around the casing 2.jpg](#)
[Well 2 Vent.jpg](#)

Kenny,

Thank you for the pictures showing the vent you installed on the sounding tube for Well #1. This addresses the significant deficiency for lack of a vent on Well #1.

In regards to Well 2 (Golf Course Well), before we remove all significant deficiencies we recommend that the well casing have a good sanitary seal to prevent contamination of the aquifer. This can be accomplished by using caulking or silicon around the metal plates to seal all openings to create a temporary seal. The issue with this is that the well is currently venting through these openings. I have attached the pictures you had previously sent us. The picture entitled "Well 2 vent 2.jpg" shows what I think is the vent for the well. It can be uncapped and some piping added to turn it downward and screened. Make sure the vent terminates at least 18 inches above the concrete pad. You could also convert the sounding tube on Well #2 to a vent, similar to what you did at Well #1. Once we get pictures of the temporary seal and vent on Well #2 we will consider the significant deficiencies at Well #2 addressed and will notify you of the closure of the 2015 sanitary survey. **The significant deficiencies at Well # 2, however, will have to be permanent corrected before you use Well 2 on an emergency basis again.**

Please call me if you have any questions.

Thank you,

José G. Rodriguez

(214) 665-8087

Rodriguez.jose@epa.gov

From: Kenny Blake [mailto:kenny@cochitigolfclub.com]

Sent: Wednesday, September 06, 2017 3:43 PM

To: Baker, JohnE ; Ngo, Kim ; Bresnahan, Meaghan

Cc: Rodriguez, Jose

Subject: Well 1 Vent - Installed 09062017

To All: Please see the attached picture of the Well 1 Screened Vent. This should take care of the remaining Significant Deficiency at Well 1.

Thanks - kb

Kenny Blake PGA | Cochiti Community Development Corporation
Chief Executive Officer

5200 Cochiti Highway
Cochiti Lake, NM 87083

T (505) 465-2210 x 11 | **F** (505) 465-0160

kenny@cochitigolfclub.com

www.cochitigolfclub.com | *Professional. Precision. Performance.*

CONFIDENTIALITY NOTICE

This e-mail and any attachments are for the sole use of the intended recipients and contain information that may be confidential or legally privileged. If you have received this e-mail in error, please notify the sender by reply e-mail and delete the message. Any disclosure, copying, distribution, or use of this communication by someone other than the intended recipient is prohibited.

